



Dart Hawkesbury
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D412-742-043
Job Sheet 166749-C



Part No: D412-742-043

Job Qty: 1 ea

Part Name: Repl. Skidtube Fits LH or RH, High Gear, DART (Apical) Tri-Bag Float Comp.



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 10/16/17

Job Tracking No:

Due Date: 10/25/17

Created By: Victoria Michaud-Febrille

Type: Stock

Description:

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Due Date	Standard		Workcenter/Supplier	
				Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time
90	Start up Operation	1 Ea	10/24/17	0.00	0.00	Start up container	18-1-09
100	DC	1 pcs	10/24/17	0.00	0.00	DC	18-1-09
110	HandFinish	1 pcs	10/25/17	0.00	3.50	HandFinish4	18-1-09
120	QC	1 pcs	10/25/17	0.00	0.00	QC5	18-1-11
130	Packaging	1 pcs	10/25/17	0.00	0.00	Packaging3	SmS
140	QC21-FG	1 Ea	10/25/17	0.00	0.00	QC21	

Part Op 100 - If D412-742-043 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-742-043 CHG007
Descriptions: 110 - 1-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment. using 7/16" "T" Pins. A/R Sikaflex-241/-291 _____ Expiry date: _____
2-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Seal all bolts with sikaflex except ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex. A/R Sikaflex-241/-291 _____ Expiry date: _____ 3-Remove "T" pins once sikaflex is dry.
4-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser. A/R LPS Procyon _____
DATE: _____ VERIFY FWD AND AFT SADDLE FIT DURING ASSEMBLY BY: _____
130 - Identify and pack for shipping as per PPP D412-742-043 Location: _____ PPP Rev: _____

Job Allocations

Operation	Component Part	Required	Inventory	Allocated	Std Qty
90-Start up Operation	AN3C4A 5019394	24	1,980	0	0
	AN3C6A PM187361-1	4	100	0	0
	AN5C7A 5019411	10	97	0	0
	D3391-021 5017282	1	1	0	0
	D3391-023 5020586	1	0	0	0
	D3391-025 5014116	1	3	0	0
	D4095-041 5006063	1	14	0	0
	D4095-043 5006094	1	6	0	0
	D4095-045 5159875	1	10	0	0
	NAS1149C0332R 5027570	28	2,674	0	0
	NAS1149C0532R 5014735	10	239	0	0

Part Specifications

Specifications could not be found.

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K64 1K7 CANADA TEL.: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com Repl. Skidtube Fits LH or RH, High Gear, DART (Apical) Tri - Bag Float Comp. PART NO: D412 - 742 - 043 Revision: Operation: Start up Operation Change No: CHG007 Mfg Date: 01/09/18 Job No: 166749 - C		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="text-align: left;">DISPOSITION</th> <th colspan="4" style="text-align: left;">AGAINST DEPARTMENT/PROCESS</th> </tr> <tr> <td style="width: 15%;">Rework ☐</td> <td style="width: 15%;">Skid-tube ☐</td> <td style="width: 15%;">Cross tube ☐</td> <td style="width: 15%;">Water Jet ☐</td> <td style="width: 15%;">Engineering ☐</td> <td style="width: 15%;"></td> </tr> <tr> <td>Wrap ☐</td> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> <td></td> </tr> <tr> <td>Is-is ☐</td> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> <td></td> </tr> <tr> <td>ved ☐</td> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> <td></td> </tr> <tr> <td colspan="3">QTY Effective :</td> <td colspan="3">MRB (QSI042) Approval</td> </tr> <tr> <td colspan="3" style="text-align: center;">Disposition</td> <td colspan="3">Completed By</td> </tr> <tr> <td colspan="3" rowspan="2"></td> <td colspan="3">Lead hand / Supervisor Approval Verification</td> </tr> <tr> <td colspan="3">QC / QA Coordinator Approval</td> </tr> </table>			DISPOSITION		AGAINST DEPARTMENT/PROCESS				Rework ☐	Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐		Wrap ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐		Is-is ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐		ved ☐	Large Fab ☐	Composite ☐	Supplier ☐			QTY Effective :			MRB (QSI042) Approval			Disposition			Completed By						Lead hand / Supervisor Approval Verification			QC / QA Coordinator Approval		
DISPOSITION		AGAINST DEPARTMENT/PROCESS																																																					
Rework ☐	Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																																																			
Wrap ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																																																			
Is-is ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																																																			
ved ☐	Large Fab ☐	Composite ☐	Supplier ☐																																																				
QTY Effective :			MRB (QSI042) Approval																																																				
Disposition			Completed By																																																				
			Lead hand / Supervisor Approval Verification																																																				
			QC / QA Coordinator Approval																																																				
 S030513 PART NO: D412 - 742 - 043 Revision: Operation: Start up Operation Change No: CHG007 Repl. Skidtube Fits LH or RH, High Gear, DART (Apical) Tri - Bag Float Comp. PART NO: D412 - 742 - 043 Revision: Operation: Start up Operation Change No: CHG007		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="3" style="text-align: left;">FAULT CATEGORY</th> </tr> <tr> <td style="width: 33%; vertical-align: top;"> ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes </td> <td style="width: 33%; vertical-align: top;"> ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center </td> <td style="width: 33%; vertical-align: top;"> ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence </td> </tr> </table>			FAULT CATEGORY			☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes	☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center	☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence																																													
FAULT CATEGORY																																																							
☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes	☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center	☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence																																																					
Past Expiry Date ☐ Misidentified ☐ Manufacturing Process ☐ Past Due ☐ OTHER : ☐																																																							